

Building - In Review

Workflow	Project Name	Coordinator	Description	Project Status	Review Cycle	Review Due Date	Current Activity
Gainesville Building Workflow	BP-18-03193-06	John Lake	Fire Sprinkler	In Review	1	9/9/2019	Department Review
Gainesville Building Workflow	BP-18-03197-06	John Lake	Fire Sprinkler	In Review	1	9/9/2019	Department Review
Gainesville Building Workflow	BP-18-03198-06	John Lake	Fire Sprinkler	In Review	1	9/9/2019	Department Review
Gainesville Building Workflow	BP-18-03199-06	John Lake	Fire Suppression	In Review	1	9/9/2019	Department Review
Gainesville Building Workflow	BP-19-05046-01 - Spa - Hub 2	Linda Patrick	Construction of small spa for Hub 2	In Review	1	9/6/2019	Department Review
Gainesville Building Workflow	BP-19-02084-06 - Fire Alarm - NFRMC Pathology Reno	John Lake	Fire Alarm	In Review	1	9/9/2019	Department Review
Gainesville Building Workflow	BP-19-05631 - Res - Alt Carport - Peterson	Charles Howe	Convert closed in carport back into carport.	In Review	1	8/20/2019	Department Review
Gainesville Building Workflow	BP-19-05491 - Sign Electrical - Savannah II	Carson Stanton	Standard installation of (2) illuminated aluminum sign cabinets on existing wall structure.	In Review	1	9/5/2019	Department Review
Gainesville Building Workflow	BP-19-05530 - Com Remodel Addison Lane Unit 270	Charles Howe	Unit 270: Level 1 Alteration	In Review	1	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-05531 - Com Remodel Addison Lane Unit 269	Charles Howe	Unit 269: Level 1 Alteration	In Review	1	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-05532 - Comm Alt - Addison Lane Unit 345	Charles Howe	Unit 345: Level 1 Alteration	In Review	1	8/23/2019	Department Review

Building - In Review

Gainesville Building Workflow	BP-19-04086 - Site Work - Harper's Pointe (DB-19-00019)	Paul Myers	Harper's Pointe: Clearing, new roads and utility infrastructure for new 6-plex and multi story building.	In Review	1	8/26/2019	Department Review
Gainesville Building Workflow	BP-19-05504 - Sign - Electrical - Kabab House	Carson Stanton	Installation of raceway mounted channel letter sign to exterior south facing building facia	In Review	1	9/6/2019	Department Review
Gainesville Building Workflow	BP-19-05498 - Sign Electrical - Sushi Matsuri	Carson Stanton	Install 1 set of wall mounted channel letters. 32.79sqft proposed. 33sqft allowed.	In Review	1	9/3/2019	Department Review
Gainesville Building Workflow	BP-19-05484 - Comm - Alt - MedMen	Charles Howe	Commercial tenant interior fit out. Conversion of (3) restaurant/bar spaces to one mercantile space. Exterior storefront replacement.	In Review	1	9/3/2019	Department Review
Gainesville Building Workflow	BP-19-05467 - Generator Install - Verizon - HCA Reg Med Ctr	Carson Stanton	remove and replace generator, remove and replace LP tank, add new 4'x10' pad within fenced lease area	In Review	1	9/2/2019	Department Review
Gainesville Building Workflow	BP-19-05464 - Comm Alt - FL Gas Utility	Charles Howe	interior remodeling, removing walls, replacing doors, ceiling grids	In Review	1	8/20/2019	Department Review
Gainesville Building Workflow	BP-19-05203 - Sign Electrical - Simed Health	Carson Stanton	Replace one ACM panel on monument sign. Install two ACM panel signs to building	In Review	2	9/2/2019	Department Review
Gainesville Building Workflow	BP-19-05391 - Res - Generator - Hutchinson	Carson Stanton	Install 22kw with 150amp transfer switch and 1 power monitorand rework service	In Review	1	9/5/2019	Department Review
Gainesville Building Workflow	BP-19-05007 - Res - Generator - Negrin	Carson Stanton	Installation of home standby generator	In Review	1	9/3/2019	Department Review
Gainesville Building Workflow	BP-19-05392 - Res - Demo - C&C	Paul Myers	Removal of duplex.	In Review	1	8/21/2019	Department Review

Building - In Review

Gainesville Building Workflow	BP-19-05343 - Sign Electrical - Gainesville 76	Carson Stanton	Install (2) 76' canopy helios on existing canopy	In Review	1	9/3/2019	Department Review
Gainesville Building Workflow	BP-19-05313 - SFD Warren Residence	Robin Rentz	New SFD Heated SqFt 1207, Total SqFt 1755	In Review	1	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-05324 - Res Site Built Carport - Cobb	Charles Howe	site built carport	In Review	1	8/19/2019	Department Review
Gainesville Building Workflow	BP-19-05317 - Comm - Alt - UF FLMNH Warehouse	Linda Patrick	HVAC System, electrical work, roofing repairs and miscellaneous repairs.	In Review	1	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-05305 - Res Solar Panels - Money	Carson Stanton	Installation of 14.3kW roof mounted photovoltaic array	In Review	1	8/27/2019	Department Review
Gainesville Building Workflow	BP-19-05315 - Res Solar Panels - BRASHER	Carson Stanton	installation of solar panels	In Review	1	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-05057 - Sign Non-Electrical - Platform Commons Monument	Charles Howe	Installing a Monument Sign	In Review	1	8/27/2019	Department Review
Gainesville Building Workflow	BP-19-05058 Sign Non-Electric - Platform Lofts Monument	Charles Howe	Install Monument Sign	In Review	1	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-05295 -SFD 506 SE 17th Ter	Paul Myers	HABITAT	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-05296 - SFD 520 SE 17th Ter	Paul Myers	HABITAT	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-05059 Sign Non-Electric - Platform Trails Monument 2	Charles Howe	Install Monument Sign & Install Plaque SIGN	In Review	1	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-04947 - Swimming Pools - INTEGRA 24 AMENITY	Linda Patrick	ADDING AMENITY SWIMMING POOL	In Review	1	8/28/2019	Department Review

Building - In Review

Gainesville Building Workflow	BP-19-05062 Sign Non Electrical - Platform Park Monument	Charles Howe	Install Monument Sign & Install Plaque Sign	In Review	1	8/27/2019	Department Review
Gainesville Building Workflow	BP-19-05250 - Res Solar Panels Chance	Carson Stanton	Solar PV	In Review	1	8/29/2019	Department Review
Gainesville Building Workflow	BP-19-05268 - Comm - Alt - Awaken Chiropractic	Charles Howe	Interior renovation, rearrangement of walls, light MEP work.	In Review	1	8/22/2019	Department Review
Gainesville Building Workflow	BP-19-05254 - Comm Site Work MetroCorp - DB-16-00129	Linda Patrick	Earthwork site drainage water sewer and paving. DB-16-00129	In Review	1	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-05252 - Comm - Alt - ASPCA Forensic	Linda Patrick	Interior remodel. New ductwork, plumbing, new wall arrangement.	In Review	1	8/26/2019	Department Review
Gainesville Building Workflow	BP-19-05241 - Com Remodel Addison Lane Bldg J	Charles Howe	Addison Lane Bldg J: soffit fascia, windows, doors and paint.	In Review	1	8/19/2019	Department Review
Gainesville Building Workflow	BP-19-05178 - Foundaion Repair - Lastinger	Charles Howe	Foundation Repair	In Review	1	8/19/2019	Department Review
Gainesville Building Workflow	BP-19-04966 - Com Sign Non-Electrical Cox Communications	Carson Stanton	Remove existing wall sign and replace with new wall sign that is 6' H x 20' W Non-Illuminated.	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-05153 - Com Sign Electrical The Oaks Mall	Carson Stanton	Remove existing (2) Sets of Channel Letters and Replace with (2) New Sets of Channel letters.	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-05036 - Com Sign Electrical FABCO AIR, INC.	Carson Stanton	Remove existing concrete and Install (1) Double sided internally LED illuminated Sign Cabinet.	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-05046 Comm Swimming Pool - Hub 2	Linda Patrick	Construction of commercial large and small spa	In Review	1	8/22/2019	Department Review

Building - In Review

Gainesville Building Workflow	BP-19-05131 - New SFD Wiltshire Lot 2	Robin Rentz	New SFD 3192 conditioned sqft. 4203 total sqft.	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-05124 - Sign Electrical - ETM	Carson Stanton	Install flash mount channel letters	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	DEMO PERMIT - GRU (Test Only) HISTORIC BUILDING	Paul Myers	Testing electronic DEMO PERMIT process - No Paper Sign-offs	In Review	1	8/5/2019	Department Review
Gainesville Building Workflow	BP-19-04790 - Swimming Pools - AAshheim Kari Leigh	Paul Myers	Inground pool and Spa	In Review	1	9/3/2019	Department Review
Gainesville Building Workflow	BP-19-05102 - Harper's Pointe Maintenance Shed	Paul Myers	construction of new storage shed: storage shed, U occupancy, type V-B	In Review	1	8/16/2019	Review Complete
Gainesville Building Workflow	BP-19-05103 - Harper's Pointe Trash Enclosure	Paul Myers	construction of new trash enclosure. U-occupancy, type V-B.	In Review	1	8/16/2019	Review Complete
Gainesville Building Workflow	BP-19-05049 - Res - Generator - Sunwall	Carson Stanton	Installation of home standby generator	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-05079-01 - Commercial New - Dunkin' - Oakwood	Linda Patrick	Construct new ground-up Dunkin' restaurant (AD-19-00021)	In Review	1	8/19/2019	Department Review
Gainesville Building Workflow	BP-19-05031 - Res - Generator - Kellett	Carson Stanton	Hookup 22kw generator with 150amp transfer switch and doing wiring for generator.	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-04944 - Res - Addition - Pais & Sieving	Charles Howe	Add 20x25 sun room on new slab.	In Review	2	8/27/2019	Department Review
Gainesville Building Workflow	BP-18-04113-04 - Res Solar Panels Finley Woods Lot 89	Carson Stanton	Installation of roof-mounted photo-voltaic system	In Review	1	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-04919 - New SFD Grand Oaks Lot 12	Robin Rentz	New SFD 681 unconditioned - > 2794 total sqft.	In Review	2	8/16/2019	Batch Stamp

Building - In Review

Gainesville Building Workflow	BP-19-04918 - New SFD Grand Oaks Lot 10	Robin Rentz	New SFD 783 unconditioned - > 2836 total sqft.	In Review	2	8/16/2019	Batch Stamp
Gainesville Building Workflow	BP-19-04934 - Comm - Generator - American Cancer Society	Carson Stanton	Install of 25KW propane generator and ATS	In Review	1	9/6/2019	Department Review
Gainesville Building Workflow	BP-19-04855 - Site Work - Store Space Self Storage	Paul Myers	Remove 4 paved entries/culverts on 4th St. Remove 2 paved entries on Main St and add sidewalks. Replace existing entry on Main street and repave driveway. Replace fencing.	In Review	1	8/29/2019	Department Review
Gainesville Building Workflow	BP-19-04891 - New SFD Grand Oaks Lot 19	Paul Myers	New SFD total sqft. 2187	In Review	1	8/19/2019	Department Review
Gainesville Building Workflow	BP-19-04890 - New SFD Grand Oaks Lot 1	Paul Myers	New SFD total sqft. 2221	In Review	1	8/19/2019	Batch Stamp
Gainesville Building Workflow	BP-19-04887 - New SFD Grand Oaks Lot 20	Paul Myers	New SFD total sqft. 2418	In Review	1	8/20/2019	Department Review
Gainesville Building Workflow	BP-19-04809 - Generator Installation - Kaleem	Carson Stanton	ATS/Generator Install	In Review	1	8/14/2019	Department Review
Gainesville Building Workflow	BP-19-04837 - Sign Electrical - KB Design	Carson Stanton	Installation of Channel Letters above west facing entrance	In Review	1	9/2/2019	Department Review
Gainesville Building Workflow	BP-19-04841 - Generator Installation - COZATT	Carson Stanton	HOOK UP 22KW GENERATOR WITH 200AMP TRANSFER SWITCH. GAS WILL PULL AND OBTAIN SEPARATE GAS PERMIT	In Review	1	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-04410 - Comm - Alt - NFRMC 2nd Floor Observat	Paul Myers	Renovation including: Demolition, Concrete, Doors/Frames, Hardware, Finishes, Div 10, MEPFP	In Review	1	8/21/2019	Department Review

Building - In Review

Gainesville Building Workflow	BP-19-04819 Comm Modular Building - Campus Circle	Paul Myers	installation of 20x24 pre-manufactured leasing trailer	In Review	1	8/26/2019	Department Review
Gainesville Building Workflow	BP-19-04626 - Generator - Loria	Carson Stanton	Install generator	In Review	2	8/20/2019	Department Review
Gainesville Building Workflow	BP-19-04696 - Curb Cut - Collins	Charles Howe	Removing existing driveway and installing pavers	In Review	2	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-04667 - Com Interior Buildout New Dunkin' Continuum	Linda Patrick	Build-out of new Dunkin' restaurant	In Review	2	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-04612 - Res Alt (Owner) - Howort	Charles Howe	enclosing carport including electrical, plumbing, mechanical	In Review	1	8/26/2019	Department Review
Gainesville Building Workflow	BP-19-04596 - Accessory Structure - Nieves	Charles Howe	Installing shipping container as storage building	In Review	2	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-04569 - Sign Electrical - Ticket Clinic	Carson Stanton	Standard installation of double faced illuminated monument sign to hook up to existing electric	In Review	2	8/21/2019	Department Review
Gainesville Building Workflow	BP-19-04547 - Sign Electrical - Wells Fargo	Carson Stanton	Installation of monument sign with new foundation.	In Review	2	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-04405 - Sign Electrical - SHELL 12931	Carson Stanton	INSTALL " SHELL IMAGE" ON EXISTING GAS STATION CANOPY AND BUILDING USING EXISTING ELECTRICITY.	In Review	2	8/27/2019	Department Review
Gainesville Building Workflow	BP-19-04337 - Driveway Apron Replacement - Vinson	Charles Howe	replace driveway apron	In Review	2	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-04166 - Res Aluminum Structure - Errico	Charles Howe	Insulated Roof over existing wood deck with post and beams	In Review	2	8/30/2019	Department Review

Building - In Review

Gainesville Building Workflow	BP-19-03986 - New SFD Villas @ 39th Lot 54	Robin Rentz	New SFD 2000sqft	In Review	2	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-03981 - New SFD Villas @ 39th Lot 9	Charles Howe	New SFD 2149sqft	In Review	2	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-03976 - New SFD Villas @ 39th Lot 8	Robin Rentz	New SFD 2149sqft	In Review	2	8/30/2019	Department Review
Gainesville Building Workflow	BP-19-03966 - New SFD Villas @ 39th Lot 7	Robin Rentz	New SFD 2397sqft	In Review	2	8/20/2019	Department Review
Gainesville Building Workflow	BP-18-05870-04 - Res Solar Panels FINLEY WOODS LOT 87	Carson Stanton	Installation of roof-mounted photovoltaic system	In Review	1	8/27/2019	Department Review
Gainesville Building Workflow	BP-19-03672 - Site Work - Walker Furniture Store Addition	Linda Patrick	Site work for DB-19-00027	In Review	1	6/25/2019	Department Review
Gainesville Building Workflow	BP-19-03672-01 - Comm - Addition - Walker Furniture Store	Linda Patrick	13,000 sqft. Conditioned. Show room, office, bathroom. (DB-19-00027) ***FLOOD***	In Review	2	7/30/2019	Review Complete
Gainesville Building Workflow	BP-19-02808-02 - Gas Canopy - Wawa #5384 AGF	Paul Myers	New construction Wawa gas canopy	In Review	2	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-02867 - Comm - Alt - GraceMarket Place - Chapel Conversion	Linda Patrick	Level III Alteration/Use Change - Convert Site Chapel into Dormatory rooms	In Review	5	8/20/2019	Department Review
Gainesville Building Workflow	BP-19-02702 - Sign Electrical - TD Bank	Carson Stanton	install signs	In Review	2	8/23/2019	Department Review
Gainesville Building Workflow	BP-19-02381 - Comm Alt - 39th Ave Clubhouse	Linda Patrick	level 2 alteration: clubhouse renovation	In Review	2	8/20/2019	Department Review
Gainesville Building Workflow	BP-18-05871-05 - Res - Solar Panels - Finley Woods Lot 90	Carson Stanton	Solar Panels 1 and 2 Family	In Review	1	8/26/2019	Department Review

Building - In Review

Gainesville Building Workflow	BP-19-02069 - Comm Alt (HISTORIC) - Rue-Kreischer Volta Inc	Paul Myers	Level II/Use Change: Renovation of existing building for a commercial prep-kitchen, restaurant supplies, and employee training	In Review	3	8/12/2019	Batch Stamp
Gainesville Building Workflow	BP-19-02082-01 Comm Addition City of Gainesville Mosquito Lab	Paul Myers	City of Gainesville Mosquito Lab Addition	In Review	4	8/29/2019	Department Review
Gainesville Building Workflow	BP-18-06114-02 - Res - Solar Panels - Finley Woods Lot 92	Carson Stanton	Installation of roof mounted photo voltaic system. Finley Woods Lot 92	In Review	1	8/28/2019	Department Review
Gainesville Building Workflow	BP-19-01667 Comm Addition & Alteration - Sonny's BBQ - Waldo Rd	Linda Patrick	Addition/Level II Alteration on Existing Sonny's: Create New Toilet Rooms and Interior Seating Changes	In Review	3	8/16/2019	Department Review
Gainesville Building Workflow	BP-19-00533 - Comm Alt - Walmart #538	Paul Myers	interior alteration to the electronic department sales floor	In Review	2	6/25/2019	Department Review
Gainesville Building Workflow	BP-18-08446 - Comm - Alt - Exactech	Linda Patrick	Level III Alteration to Original Exactech Building	In Review	1	8/23/2019	Department Review
Gainesville Building Workflow	BP-18-07595 Site Work - Waffle House Universty Ave (AD-18-00098)	Paul Myers	Site Work and paving for new Waffle House (AD-18-00098)	In Review	1	12/10/2018	Department Review
Gainesville Building Workflow	BP-18-07595-01 - Comm New - Waffle House	Paul Myers	New waffle house restaurant: total 1775 sqft ***Hold for Planning AD-18-00098***	In Review	3	3/15/2019	Batch Stamp
Gainesville Building Workflow	BP-18-04725-02 New Parking Garage - Campus Advantage	Linda Patrick	new construction of a 6-level precast concrete parking decktotal 177,075 sqft	In Review	1	7/26/2019	Department Review
Gainesville Building Workflow	BP-18-04379 - Site Work - The Quad (DB-18-00043)	Paul Myers	Site Work - earth work, paving, concrete and utilities to facilitate new construction	In Review	1	7/26/2019	Review Complete

Building - In Review

Gainesville Building Workflow	BP-18-03113 New Apartments 8-Plex #3041 - Serenola Manor	Paul Myers	New Apartments - 2 story 8 unit apartment building 5131 total sq ft (DB 16-00048)	In Review	3	8/19/2019	Batch Stamp
Gainesville Building Workflow	BP-18-03117 New Apartments 8-Plex #3051 - Serenola Manor	Paul Myers	New Apartments - 2 story 8 unit apartments. 5131 total sq ft (DB 16-00048)	In Review	3	8/19/2019	Department Review
Gainesville Building Workflow	BP-18-03122 New Apartments 6-Plex #3061 - Serenola Manor	Paul Myers	New Apartments - 2 story apartments. 6 Units. 3858 total sq ft (DB 16-00048)	In Review	4	8/20/2019	Department Review
Gainesville Building Workflow	BP-18-01112 - Res repairs - Meyer	Charles Howe	Repairs and replacement of exterior as needed	In Review	2	8/20/2019	Department Review
Gainesville Building Workflow	BP-17-05720 Site Work - 800 Second (DB-16-00153)	Paul Myers	Site Work (5/20/19 - Workflow paused due to no activity - ptm)	In Review	1	3/25/2019	Department Review